

3/6




FIG. 3A




FIG. 3B

ILTs 20 and dip pad 39  
being made same thickness  
as OLTs 12



4/6




FIG. 4




FIG. 5



5/6




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8



6/6




FIG. 9




FIG. 10